




The foreshore near the 'former' Ascot Inn. A major missing link in the path network.



The old, narrow concrete paths and the narrow boardwalk at the eastern end of Garvey Park will need to be upgraded.



Private jetties and steep embankments (as is the case along Fauntleroy Ave) will require an innovative solution, such as a floating boardwalk.

